

## Product: Vinyl floor tiles and covering

<b>Product Name</b>	Vinyl floor tiles and covering
<b>Product type</b>	Floor Covering
<b>Sub-Product type</b>	Floor Tiles
<b>Trading name(s)</b>	
<b>Other name(s)</b>	Floor tiles, vinyl floor, plastic tiles, lino or linoleum.
<b>Product description</b>	<p>Solid, brittle material in a variety of colours used in control rooms, bathrooms, common rooms and amenities rooms of zone substations and Field Service Centres. Sometimes used in bigger distribution substations.</p> <p>Can also be referred to as lino or linoleum.</p>
<b>Build element</b>	Construction
<b>Product identification</b>	
Asbestos-containing vinyl floor tiles can have a variety of colours and shapes, but they will look exactly the same as non-asbestos-containing vinyl floor tiles. Reliable identification can only be achieved by laboratory analysis.	
<b>Known uses</b>	Durable flooring
<b>Asbestos fibre type</b>	Chrysotile (white asbestos)
<b>Friable or Non-Friable</b>	Non-Friable
<b>Known Supplier(s)</b>	
<b>Known place of manufacture</b>	
<b>Date / period of manufacture</b>	Pre 1987
<b>Building construction period</b>	1931-1940, 1941-1950, 1951-1960, 1961-1970, 1970-1980, 1981-1990
<b>Location</b>	<p><b>Domestic home</b></p> <ul style="list-style-type: none"> <li>• Bathroom</li> <li>• Dining room</li> <li>• Dog kennels</li> <li>• Fencing</li> <li>• Fireplace</li> <li>• Flooring &amp; covering</li> <li>• Kitchen</li> <li>• Laundry</li> <li>• Toilet</li> </ul> <p><b>Commercial</b></p> <ul style="list-style-type: none"> <li>• Flooring</li> <li>• Wet Areas (Bathrooms/toilets etc)</li> </ul> <p><b>Industrial</b></p>

- Flooring

## Plant

Other Public

### Product images



Asbestos Homes 101.JPG

<b>Name</b>	Vinyl Floor Covering - Commercial
<b>Caption</b>	Commercial Vinyl Floor Covering which contains asbestos in the backing
<b>Location</b>	Commercial
<b>Source</b>	Asbestos Education Committee
<b>Image Id</b>	93



IMG\_0103.jpg

<b>Name</b>	Vinyl Floor Covering - Kitchen 1
<b>Caption</b>	Domestic vinyl floor covering in a kitchen - it is lifting at the base of the cupboard
<b>Location</b>	Domestic home
<b>Source</b>	Asbestos Education Committee
<b>Image Id</b>	94



IMG\_0124.jpg

<b>Name</b>	Vinyl Floor Covering - Kitchen 1b
<b>Caption</b>	Domestic vinyl floor covering in a kitchen and laundry which pictures the underside of a loose section
<b>Location</b>	Domestic home
<b>Source</b>	Asbestos Education Committee
<b>Image Id</b>	95



IMG\_0156.jpg


<b>Name</b>	Vinyl Floor meets Capet
<b>Caption</b>	Domestic vinyl floor covering which meets carpet.
<b>Location</b>	Domestic home
<b>Source</b>	Asbestos Education Committee
<b>Image Id</b>	96



Vinyl Floor Tiles - photo courtesy of Townsville Asbestos.jpg

<b>Name</b>	Lino Floor Tiles
<b>Caption</b>	Comercial lino floor tiles
<b>Location</b>	Commercial

Source	Townsville Asbestos
Image Id	97



Vinyl floor tiles damaged - photo courtesy of Townsville Asbestos.jpg

Name	Lino Floor Tiles
Caption	Commercial lino floor tiles - damaged
Location	Commercial
Source	Townsville Asbestos
Image Id	98



JBIFloor Covering - Confirmed\_.jpg

Name	Vinyl Floor Covering - Kitchen 2
Caption	Domestic vinyl floor covering in a kitchen which has been partially removed exposing asbestos cement floor and adhesive.
Location	Domestic home
Source	Jim's Building Inspections
Image Id	230




JB\_I\_Vinyl Floor Covering - Confirmed (2).jpg

<b>Name</b>	Domestic Vinyl Floor Covering
<b>Caption</b>	Domestic vinyl floor covering
<b>Location</b>	Domestic home
<b>Source</b>	Jim's Building Inspections
<b>Image Id</b>	231



JB\_I\_Vinyl Floor Covering - Confirmed.jpg

<b>Name</b>	Domestic Vinyl Floor Covering - toilet
<b>Caption</b>	Domestic vinyl floor covering in a toilet and bathroom
<b>Location</b>	Domestic home
<b>Source</b>	Jim's Building Inspections
<b>Image Id</b>	232



865.jpg

<b>Name</b>	Remnants of Asbestos backed vinyl flooring
<b>Caption</b>	Asbestos backed vinyl sheet flooring. The green material indicates the backing which contains asbestos.
<b>Location</b>	Industrial




<b>Source</b>	SHAPE Group
<b>Image Id</b>	267



1119.jpg

<b>Name</b>	Vinyl Floor Covering - Commercial
<b>Caption</b>	Vinyl floor tile with backing that contains asbestos.
<b>Location</b>	Commercial
<b>Source</b>	SHAPE Group
<b>Image Id</b>	268



WST\_blackjack-glue.jpg

<b>Name</b>	Close up Vinyl Floor Covering - Commercial
<b>Caption</b>	Asphaltic cutback adhesive under vinyl tiles
<b>Location</b>	Commercial
<b>Source</b>	WorkSafe Tasmania
<b>Image Id</b>	269



WST\_vinyl-flooring.jpg

<b>Name</b>	Vinyl Floor Covering in public building
<b>Caption</b>	Vinyl Floor Covering in public building
<b>Location</b>	Other
<b>Source</b>	WorkSafe Tasmania
<b>Image Id</b>	270



WST\_vinyl-floor-tiles.jpg

<b>Name</b>	Vinyl Floor Covering
<b>Caption</b>	Asphaltic cutback adhesive under vinyl tiles
<b>Location</b>	Commercial
<b>Source</b>	WorkSafe Tasmania
<b>Image Id</b>	271



IMGP1527.JPG

<b>Name</b>	Close up Vinyl Floor Covering - Commercial
<b>Caption</b>	Close up Vinyl Floor Covering - Commercial
<b>Location</b>	Commercial

Source	Prensa
Image Id	357



IMGP1533.JPG

Name	Vinyl Floor Covering - Commercial
Caption	Vinyl Floor Covering - Commercial
Location	Commercial
Source	Prensa
Image Id	358



IMGP1536.JPG

Name	Close up Vinyl Floor Covering - Commercial
Caption	Close up Vinyl Floor Covering - Commercial
Location	Commercial
Source	Prensa
Image Id	359



IMG\_0502.JPG




<b>Name</b>	Vinyl flooring as liner
<b>Caption</b>	Vinyl flooring used as shelf liner in bathroom
<b>Location</b>	Domestic home
<b>Source</b>	Asbestos Awareness
<b>Image Id</b>	368



asbestos paper under lino.jpg

<b>Name</b>	Asbestos paper under lino
<b>Caption</b>	Asbestos paper under lino
<b>Location</b>	Domestic home
<b>Source</b>	Prensa
<b>Image Id</b>	369



Lino Floor 1783 Courtesy Asbestos Awareness.JPG

<b>Name</b>	Lino Tiles - BW
<b>Caption</b>	Domestic lino floor tiles
<b>Location</b>	Domestic home
<b>Source</b>	Asbestos Awareness
<b>Image Id</b>	370



DSC\_0155.JPG

<b>Name</b>	Lino Tiles - lifting
<b>Caption</b>	Commercial lino floor tiles - lifting
<b>Location</b>	Commercial
<b>Source</b>	Asbestos Awareness
<b>Image Id</b>	371



DSC\_0161.JPG

<b>Name</b>	Commercial Lino Tiles
<b>Caption</b>	Commercial lino floor tiles - lifting
<b>Location</b>	Commercial
<b>Source</b>	Asbestos Awareness
<b>Image Id</b>	372



IMG\_0090.JPG

<b>Name</b>	Domestic Vinyl Floor Covering
<b>Caption</b>	Domestic vinyl floor covering
<b>Location</b>	Domestic home

Source	Asbestos Awareness
Image Id	373

---

