

Product: Vinyl floor tiles and covering

Product Name	Vinyl floor tiles and covering
Product type	Floor Covering
Sub-Product type	Floor Tiles
Trading name(s)	
Other name(s)	Floor tiles, vinyl floor, plastic tiles, lino or linoleum.
Product description	<p>Solid, brittle material in a variety of colours used in control rooms, bathrooms, common rooms and amenities rooms of zone substations and Field Service Centres. Sometimes used in bigger distribution substations.</p> <p>Can also be referred to as lino or linoleum.</p>
Build element	Construction
Product identification	
Asbestos-containing vinyl floor tiles can have a variety of colours and shapes, but they will look exactly the same as non-asbestos-containing vinyl floor tiles. Reliable identification can only be achieved by laboratory analysis.	
Known uses	Durable flooring
Asbestos fibre type	Chrysotile (white asbestos)
Friable or Non-Friable	Non-Friable
Known Supplier(s)	
Known place of manufacture	
Date / period of manufacture	Pre 1987
Building construction period	1931-1940, 1941-1950, 1951-1960, 1961-1970, 1970-1980, 1981-1990
Location	<p>Domestic home</p> <ul style="list-style-type: none"> • Bathroom • Dining room • Dog kennels • Fencing • Fireplace • Flooring & covering • Kitchen • Laundry • Toilet <p>Commercial</p> <ul style="list-style-type: none"> • Flooring • Wet Areas (Bathrooms/toilets etc) <p>Industrial</p>

- Flooring

Plant

Other Public

Product images



Asbestos Homes 101.JPG

Name	Vinyl Floor Covering - Commercial
Caption	Commercial Vinyl Floor Covering which contains asbestos in the backing
Location	Commercial
Source	Asbestos Education Committee
Image Id	93



IMG_0103.jpg

Name	Vinyl Floor Covering - Kitchen 1
Caption	Domestic vinyl floor covering in a kitchen - it is lifting at the base of the cupboard
Location	Domestic home
Source	Asbestos Education Committee
Image Id	94



IMG_0124.jpg

Name	Vinyl Floor Covering - Kitchen 1b
Caption	Domestic vinyl floor covering in a kitchen and laundry which pictures the underside of a loose section
Location	Domestic home
Source	Asbestos Education Committee
Image Id	95



IMG_0156.jpg


Name	Vinyl Floor meets Capet
Caption	Domestic vinyl floor covering which meets carpet.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	96



Vinyl Floor Tiles - photo courtesy of Townsville Asbestos.jpg

Name	Lino Floor Tiles
Caption	Comercial lino floor tiles
Location	Commercial

Source	Townsville Asbestos
Image Id	97



Vinyl floor tiles damaged - photo courtesy of Townsville Asbestos.jpg

Name	Lino Floor Tiles
Caption	Commercial lino floor tiles - damaged
Location	Commercial
Source	Townsville Asbestos
Image Id	98



JBIFloor Covering - Confirmed_.jpg

Name	Vinyl Floor Covering - Kitchen 2
Caption	Domestic vinyl floor covering in a kitchen which has been partially removed exposing asbestos cement floor and adhesive.
Location	Domestic home
Source	Jim's Building Inspections
Image Id	230




JB_I_Vinyl Floor Covering - Confirmed (2).jpg

Name	Domestic Vinyl Floor Covering
Caption	Domestic vinyl floor covering
Location	Domestic home
Source	Jim's Building Inspections
Image Id	231



JB_I_Vinyl Floor Covering - Confirmed.jpg

Name	Domestic Vinyl Floor Covering - toilet
Caption	Domestic vinyl floor covering in a toilet and bathroom
Location	Domestic home
Source	Jim's Building Inspections
Image Id	232



865.jpg


Name	Remnants of Asbestos backed vinyl flooring
Caption	Asbestos backed vinyl sheet flooring. The green material indicates the backing which contains asbestos.
Location	Industrial

Source	SHAPE Group
Image Id	267



1119.jpg

Name	Vinyl Floor Covering - Commercial
Caption	Vinyl floor tile with backing that contains asbestos.
Location	Commercial
Source	SHAPE Group
Image Id	268



WST_blackjack-glue.jpg

Name	Close up Vinyl Floor Covering - Commercial
Caption	Asphaltic cutback adhesive under vinyl tiles
Location	Commercial
Source	WorkSafe Tasmania
Image Id	269



WST_vinyl-flooring.jpg

Name	Vinyl Floor Covering in public building
Caption	Vinyl Floor Covering in public building
Location	Other
Source	WorkSafe Tasmania
Image Id	270



WST_vinyl-floor-tiles.jpg

Name	Vinyl Floor Covering
Caption	Asphaltic cutback adhesive under vinyl tiles
Location	Commercial
Source	WorkSafe Tasmania
Image Id	271



IMGP1527.JPG

Name	Close up Vinyl Floor Covering - Commercial
Caption	Close up Vinyl Floor Covering - Commercial
Location	Commercial

Source	Prensa
Image Id	357



IMGP1533.JPG

Name	Vinyl Floor Covering - Commercial
Caption	Vinyl Floor Covering - Commercial
Location	Commercial
Source	Prensa
Image Id	358



IMGP1536.JPG

Name	Close up Vinyl Floor Covering - Commercial
Caption	Close up Vinyl Floor Covering - Commercial
Location	Commercial
Source	Prensa
Image Id	359




IMG_0502.JPG

Name	Vinyl flooring as liner
Caption	Vinyl flooring used as shelf liner in bathroom
Location	Domestic home
Source	Asbestos Awareness
Image Id	368



asbestos paper under lino.jpg

Name	Asbestos paper under lino
Caption	Asbestos paper under lino
Location	Domestic home
Source	Prensa
Image Id	369



Lino Floor 1783 Courtesy Asbestos Awareness.JPG

Name	Lino Tiles - BW
Caption	Domestic lino floor tiles
Location	Domestic home
Source	Asbestos Awareness
Image Id	370



DSC_0155.JPG

Name	Lino Tiles - lifting
Caption	Commercial lino floor tiles - lifting
Location	Commercial
Source	Asbestos Awareness
Image Id	371



DSC_0161.JPG

Name	Commercial Lino Tiles
Caption	Commercial lino floor tiles - lifting
Location	Commercial
Source	Asbestos Awareness
Image Id	372



IMG_0090.JPG

Name	Domestic Vinyl Floor Covering
Caption	Domestic vinyl floor covering
Location	Domestic home

Source	Asbestos Awareness
Image Id	373
