



## **Product:** Door, Window, Cornice & Joining Strip Mouldings

Product Door, Window, Cornice & Joining Strip Mouldings Name

**Product type** Asbestos Cement Fixings

Sub-Product type

Trading

name(s)
Other

architrave

name(s)
Product
description

Used as architrave around doors and windows, window sills also used a AC sheet joining strips can have plain or spigoted ends, including louvre blades, also used as cornices. A round nail can be visible on the strip, usually just above surface. Commonly used as joining strips, window and door architrave.

Build element

Construction

Product identification

Round nail visible on the strip, usually just above surface. Commonly used as joining strips, window and door architrave.

Known uses Commonly used as joining strips, cornices, window and door architrave.

Asbestos fibre type

Chrysotile (white asbestos)

Friable or Non-Friable

Non-Friable

Known Supplier(s)

James Hardie

Known place

of manufacture

Date / period

of manufacture

Building construction period

1900-1920,1921-1930,1931-1940,1941-1950,1951-1960,1961-1970,1970-1980,1981-1990,Pre 1900

#### Location

#### **Domestic home**

- Bathroom
- Ceiling / Ceiling space
- Dining room
- Dog kennels
- Exterior
- Internal walls
- · Mouldings internal and external
- Windows / Doors

#### Commercial

- Doors
- Moulded Product
- Windows

#### **Industrial**

- Doors
- Moulded Product

# **Product** images



## $IMG\_0130.jpg$

Name Asbestos window trim

**Caption** Window architrave made from moulded asbestos cement

**Location** Domestic home

**Source** Asbestos Education Committee

**Image Id** 46



IMG 0131.jpg

Name Asbestos window trim 2

Caption Window architrave made from moulded asbestos cement

**Location** Domestic home

**Source** Asbestos Education Committee




Name James Hardie Product Information PDF - Window and Door Mouldings

Caption James Hardie Product Information PDF - Window and Door Mouldings

Location Other

Source Archive

Image Id 167



### AC Ceiling. IPG

710 00mmg.jr 0			
Name	Ceiling joining strip		
Caption	Joining strips on AC sheeting ceiling		
Location	Commercial		
Source	Prensa		
Image Id	335		



## AAD WCS 031.JPG

Name AC Cornice & Door Architrave

Caption AC Cornice & Door Architrave, AC Wall and Ceiling

**Location** Domestic home

**Source** Asbestos Awareness



AAD WCS 013.JPG

Name	Exterior Joining Strips			
Caption	Exterior Joining Strips			
Location	Domestic home			
Source	Asbestos Awareness			
Image Id	337			



Internal Ceiling 2550 Courtesy Asbestos Awareness.JPG

Name	Ceiling joining strip
Caption	Ceiling joining strips
Location	Domestic home
Source	Asbestos Awareness
Image Id	338



0075AsbestosProduct.JPG

Name	Exterior Joining Strips
Caption	Broken exterior / external moulded asbestos joining strips on AC wall
Location	Domestic home

Source	Asbestos Awareness
Image Id	339



External Walls 2336 Courtesy Asbestos Awareness.JPG


Name Exterior Joining Strips on AC cement wall

**Caption** Exterior Joining Strips on AC cement wall

**Location** Domestic home

**Source** Asbestos Awareness

**Image Id** 340



Exterior moulded asbestos joining strip 073.JPG

Name Exterior Joining Strip & Capping on AC cement wall

Caption Close up of exterior joining strip end and corner capping on AC cement wall

**Location** Domestic home

**Source** Asbestos Awareness



Moulded asbestos corner capping731.JPG

Name Exterior Corner Capping

**Caption** Moulded exterior AC corner capping. Identifiable through the slightly raised nails.

**Location** Commercial

**Source** Asbestos Awareness

**Image Id** 364



Asbestos Cement Walls 0296.JPG

Name AC wall with joining strips

**Caption** Asbestos cement wall with moulded asbestos joining strips.

**Location** Domestic home

**Source** Asbestos Awareness

**Image Id** 376



## IMG\_0138.jpg

## Name

**Caption** Asbestos cement ceiling and wall with moulded asbestos joining strips and cornice.

**Location** Domestic home

**Source** Asbestos Awareness

Image Id 377



IMG\_0163.jpg

Name AC wall with moulded asbestos joining strips

**Caption** Asbestos cement wall with moulded asbestos joining strips.

**Location** Domestic home

**Source** Asbestos Awareness

Image Id 378



## 0068 Asbestos Product. JPG

Name Moulded Asbestos Cornice

**Caption** Moulded Asbestos Cornice on AC wall and ceiling

**Location** Domestic home

**Source** Asbestos Awareness