

Product: Plaster

| | |
|-------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Product Name | Plaster |
| Product type | Adhesives, mastics, putty, sealants, plasters and paints |
| Sub-Product type | |
| Trading name(s) | |
| Other name(s) | |
| Product description | A stucco or render building material used for coating walls and ceilings. It is manufactured as a dry powder and is mixed with water to form a paste when used. |
| Build element | |
| Product identification | |
| Known uses | Interior plaster work |
| Asbestos fibre type | Chrysotile (white asbestos) |
| Friable or Non-Friable | Friable |
| Known Supplier(s) | |
| Known place of manufacture | |
| Date / period of manufacture | |
| Building construction period | 1941-1950,1951-1960,1961-1970,1970-1980,1981-1990 |
| Location | <p>Domestic home</p> <ul style="list-style-type: none"> • Bathroom • Bedroom • Ceiling / Ceiling space • Dining room • Dog kennels • Hallway • Internal walls • Kitchen • Living room • Mouldings - internal and external <p>Commercial</p> <ul style="list-style-type: none"> • Walls <p>Industrial</p> <ul style="list-style-type: none"> • Walls |
| Product images | |



Plaster Ceiling DSCN7848.jpg

Name Plaster ACM Ceiling

Caption Domestic livingroom ceiling with plaster which contains asbestos.

Location Domestic home

Source WorkSafe New Zealand

Image Id 302



Plaster DSCN7854.jpg

Name Plaster ACM Ceiling

Caption Domestic bedroom ceiling with plaster which contains asbestos.

Location Domestic home

Source WorkSafe New Zealand

Image Id 303



Decorative Ceiling 1-nz.jpg

Name Decorative ceiling

Caption Decorative ceiling with asbestos containing material

Location Domestic home

Source WorkSafe New Zealand

Image Id 314



Decorative Ceiling 2 nz.jpg

Name Close up of decorative ceiling

Caption Close up of decorative ceiling with asbestos containing material

Location Domestic home

Source WorkSafe New Zealand

Image Id 315

