

Product: Tilux - Wet-area fibrous asbestos cement sheet

Product Name	Tilux - Wet-area fibrous asbestos cement sheet
Product type	Cement - sheets, moulded product
Sub-Product type	
Trading name(s)	Tilux
Other name(s)	
Product description	Compressed and autoclaved, coloured and patterned waterproof cement sheeting, used mainly in kitchens, bathrooms and laundries
Build element	Construction
Product identification	
Tilux sheets were attached to walls and used as splashbacks in bathrooms and kitchens, as shower recesses and bathroom walls. The stainless steel strip between sheets is a primary indicator. The sheets were patterned and often in shades of pink, blue, green and grey. The surface is coated and can be a dull matt appearance or shiny.	
Known uses	Wall lining or tiling in kitchens, bathrooms and laundries
Asbestos fibre type	Amosite (brown asbestos) Chrysotile (white asbestos) Crocidolite (blue asbestos)
Friable or Non-Friable	Non-Friable
Known Supplier(s)	James Hardie
Known place of manufacture	
Date / period of manufacture	Pre 1987
Building construction period	1900-1920, 1921-1930, 1931-1940, 1941-1950, 1951-1960, 1961-1970, 1970-1980, 1981-1990, Pre 1900
Location	Domestic home <ul style="list-style-type: none"> • Bathroom • Dining room • Kitchen • Laundry • Toilet Commercial <ul style="list-style-type: none"> • Building structure • Walls • Wet Areas (Bathrooms/toilets etc)
Product images	



0062AsbestosProduct.JPG

Name	Tilux 1
Caption	Close up of Tilux on partition wall
Location	Domestic home
Source	Asbestos Education Committee
Image Id	170



0067AsbestosProduct.JPG


Name	Tillux - damaged
Caption	Close up of damaged section of Tilux from a laundry. The broken corner exposes the fibres.
Location	
Source	Asbestos Education Committee
Image Id	171



0093AsbestosProduct.JPG

Name	Asbestos cement wall behind Tilux
Caption	Asbestos cement wall behind Tilux
Location	Domestic home

Source	Asbestos Education Committee
Image Id	172



TILUX_0093.JPG

Name	Tilux - Springtime Blue Close Up
Caption	Close up photo of Tilux in Springtime Blue pattern. The silver screw holding it to the wall, visible in this photo, is an indicator that the material you have may be asbestos containing Tilux.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	173



TILUX_0094.JPG

Name	Tilux - Springtime Blue Joins
Caption	Tilux in Springtime Blue pattern. The silver metal cover strips, visible in this photo, indicate the material would be Tilux.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	174



IMG_0077.JPG

Name	Tilux walls - Hazard
Caption	The Tilux in this bathroom is a hazard. Due to years of scrubbing, the outer sealed layer has been cleaned off creating fine dust which would contain asbestos.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	176



IMG_0083.JPG

Name	Tilux Shower and Asbestos
Caption	The Tilux in this bathroom is a hazard. Due to years of scrubbing, the outer sealed layer has been cleaned off creating a fine dust which would contain asbestos. The upper walls are also asbesto cement, the flooring beneath the tiles and the grout also contain asbestos containing materials.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	177



IMG_0085.JPG

Name	Tilux bathroom walls - hazard
Caption	The Tilux in this bathroom is a hazard. Due to years of scrubbing, the outer sealed layer has been cleaned off creating fine dust which would contain asbestos.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	178



IMG_0092.JPG

Name	Tilux kitchen splash back
Caption	Well maintained Tilux sheeting used as a kitchen splash back.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	179



IMG_0093.JPG

Name	Tilux kitchen splash back
Caption	Well maintained Tilux sheeting used as a kitchen splash-back. Tilux has been cut to accommodate cupboards.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	180



IMG_0108.JPG

Name	Tilux kitchen splashback - lose up
Caption	Tilux sheeting used as a kitchen splash back. Tilux has been cut around the window creating an exposed gap..
Location	Domestic home
Source	Asbestos Education Committee
Image Id	181



IMG_0109.JPG

Name	Tilux kitchen splashback
Caption	Tilux sheeting used as a kitchen splash back. The silver metal cover strips, visible in this photo, indicate the material would be Tilux.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	182



IMG_0110.JPG

Name	Tilux kitchen splashback and laminate bench
Caption	The silver metal cover strips, visible in this photo, indicate the material would be Tilux. The glue under the laminate bench top may contain asbestos.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	183



IMG_0111.JPG

Name	Tilux kitchen splashback
Caption	The silver metal cover strips and metal screw visible in this photo, indicate the material would be Tilux.
Location	Domestic home
Source	Asbestos Education Committee
Image Id	184



PRODUCT INFORMATION

TILUX - Asbestos Industry Association Hardie Asbestos Products.pdf

Name	James Hardie Product Information PDF - Tilux
Caption	James Hardie Product Information PDF - Tilux
Location	Other
Source	Archive
Image Id	185



image.jpeg

Name	Tilux - original label
Caption	Original Tilux instruction sheet attached to back of Tilux wall sheet
Location	Domestic home
Source	Asbestos Awareness
Image Id	327



tilux 2.jpeg

Name	Tilux with original label
Caption	Original Tilux instruction sheet attached to back of Tilux wall sheet
Location	Domestic home
Source	Asbestos Awareness
Image Id	328

