

Product: Door, Window, Cornice & Joining Strip Mouldings

Product Name	Door, Window, Cornice & Joining Strip Mouldings
Product type	Asbestos Cement Fixings
Sub-Product type	
Trading name(s)	
Other name(s)	architrave
Product description	Used as architrave around doors and windows, window sills also used a AC sheet joining strips can have plain or spigoted ends, including louvre blades, also used as cornices. A round nail can be visible on the strip, usually just above surface. Commonly used as joining strips, window and door architrave.
Build element	Construction
Product identification	
	Round nail visible on the strip, usually just above surface. Commonly used as joining strips, window and door architrave.
Known uses	Commonly used as joining strips, cornices, window and door architrave.
Asbestos fibre type	Chrysotile (white asbestos)
Friable or Non-Friable	Non-Friable
Known Supplier(s)	James Hardie
Known place of manufacture	
Date / period of manufacture	
Building construction period	1900-1920,1921-1930,1931-1940,1941-1950,1951-1960,1961-1970,1970-1980,1981-1990,Pre 1900
Location	<p>Domestic home</p> <ul style="list-style-type: none"> • Bathroom • Ceiling / Ceiling space • Dining room • Dog kennels • Exterior • Internal walls • Mouldings - internal and external • Windows / Doors <p>Commercial</p> <ul style="list-style-type: none"> • Doors • Moulded Product • Windows <p>Industrial</p> <ul style="list-style-type: none"> • Doors • Moulded Product

- Windows

Product images



IMG_0130.jpg

Name	Asbestos window trim
Caption	Window architrave made from moulded asbestos cement
Location	Domestic home
Source	Asbestos Education Committee
Image Id	46



IMG_0131.jpg

Name	Asbestos window trim 2
Caption	Window architrave made from moulded asbestos cement
Location	Domestic home
Source	Asbestos Education Committee
Image Id	47



PRODUCT INFORMATION

Name	James Hardie Product Information PDF - Window and Door Mouldings
Caption	James Hardie Product Information PDF - Window and Door Mouldings
Location	Other
Source	Archive
Image Id	167




AC Ceiling.JPG

Name	Ceiling joining strip
Caption	Joining strips on AC sheeting ceiling
Location	Commercial
Source	Prensa
Image Id	335



AAD WCS 031.JPG

Name	AC Cornice & Door Architrave
Caption	AC Cornice & Door Architrave, AC Wall and Ceiling
Location	Domestic home
Source	Asbestos Awareness
Image Id	336






AAD WCS 013.JPG

Name	Exterior Joining Strips
Caption	Exterior Joining Strips
Location	Domestic home
Source	Asbestos Awareness
Image Id	337



Internal Ceiling 2550 Courtesy Asbestos Awareness.JPG

Name	Ceiling joining strip
Caption	Ceiling joining strips
Location	Domestic home
Source	Asbestos Awareness
Image Id	338



0075AsbestosProduct.JPG

Name	Exterior Joining Strips
Caption	Broken exterior / external moulded asbestos joining strips on AC wall
Location	Domestic home

Source Asbestos Awareness

Image Id 339



External Walls 2336 Courtesy Asbestos Awareness.JPG


Name Exterior Joining Strips on AC cement wall

Caption Exterior Joining Strips on AC cement wall

Location Domestic home

Source Asbestos Awareness

Image Id 340



Exterior moulded asbestos joining strip 073.JPG

Name Exterior Joining Strip & Capping on AC cement wall

Caption Close up of exterior joining strip end and corner capping on AC cement wall

Location Domestic home

Source Asbestos Awareness

Image Id 363



Moulded asbestos corner capping731.JPG

Name Exterior Corner Capping

Caption Moulded exterior AC corner capping. Identifiable through the slightly raised nails.

Location Commercial

Source Asbestos Awareness

Image Id 364



Asbestos Cement Walls_0296.JPG


Name AC wall with joining strips

Caption Asbestos cement wall with moulded asbestos joining strips.

Location Domestic home

Source Asbestos Awareness

Image Id 376



IMG_0138.jpg

Name

Caption Asbestos cement ceiling and wall with moulded asbestos joining strips and cornice.

Location Domestic home

Source Asbestos Awareness

Image Id 377



IMG_0163.jpg

Name AC wall with moulded asbestos joining strips

Caption Asbestos cement wall with moulded asbestos joining strips.

Location Domestic home

Source Asbestos Awareness

Image Id 378



0068AsbestosProduct.JPG

Name Moulded Asbestos Cornice

Caption Moulded Asbestos Cornice on AC wall and ceiling

Location Domestic home

Source Asbestos Awareness

Image Id 397
