


## Product: Wall vents

<b>Product Name</b>	Wall vents
<b>Product type</b>	Adhesives, mastics, putty, sealants, plasters and paints
<b>Sub-Product type</b>	
<b>Trading name(s)</b>	
<b>Other name(s)</b>	
<b>Product description</b>	Asbestos containing material has been found in wall vents used for ventilation in domestic homes.
<b>Build element</b>	Ventilation
<b>Product identification</b>	
<b>Known uses</b>	Wall ventilation
<b>Asbestos fibre type</b>	
<b>Friable or Non-Friable</b>	Non-Friable
<b>Known Supplier(s)</b>	
<b>Known place of manufacture</b>	
<b>Date / period of manufacture</b>	Pre 1987
<b>Building construction period</b>	1941-1950,1951-1960,1961-1970,1970-1980,1981-1990
<b>Location</b>	<p><b>Domestic home</b></p> <ul style="list-style-type: none"> <li>• Bathroom</li> <li>• Bedroom</li> <li>• Dining room</li> <li>• Dog kennels</li> <li>• Hallway</li> <li>• Internal walls</li> <li>• Kitchen</li> <li>• Laundry</li> <li>• Living room</li> </ul> <p><b>Commercial</b></p> <ul style="list-style-type: none"> <li>• Walls</li> </ul> <p><b>Industrial</b></p>
<b>Product images</b>	



IMG\_0122.jpg

<b>Name</b>	Wall Vent
<b>Caption</b>	Internal wall vent
<b>Location</b>	Domestic home
<b>Source</b>	Asbestos Education Committee
<b>Image Id</b>	43



IMG\_1264.JPG

<b>Name</b>	Wall Vent in kitchen
<b>Caption</b>	Wall Vent in kitchen
<b>Location</b>	Domestic home
<b>Source</b>	Asbestos Education Committee
<b>Image Id</b>	320



IMG\_1261.JPG

<b>Name</b>	Asbestos in the Bathroom
<b>Caption</b>	Asbestos cement sheeting in walls and ceiling, adhesive behind tiles, in grout and ceiling vent.
<b>Location</b>	Domestic home

**Source** Asbestos Education Committee

**Image Id** 321



IMG\_1263.JPG

**Name** Asbestos vent in bathroom

**Caption** Ceiling vent in bathroom

**Location** Domestic home

**Source** Asbestos Education Committee

**Image Id** 322

