


## Product: Wall vents

<b>Product Name</b>	Wall vents
<b>Product type</b>	Adhesives, mastics, putty, sealants, plasters and paints
<b>Sub-Product type</b>	
<b>Trading name(s)</b>	
<b>Other name(s)</b>	
<b>Product description</b>	Asbestos containing material has been found in wall vents used for ventilation in domestic homes.
<b>Build element</b>	Ventilation
<b>Product identification</b>	
<b>Known uses</b>	Wall ventilation
<b>Asbestos fibre type</b>	
<b>Friable or Non-Friable</b>	Non-Friable
<b>Known Supplier(s)</b>	
<b>Known place of manufacture</b>	
<b>Date / period of manufacture</b>	Pre 1987
<b>Building construction period</b>	1941-1950,1951-1960,1961-1970,1970-1980,1981-1990
<b>Location</b>	<b>Domestic home</b> <ul style="list-style-type: none"> <li>• Bathroom</li> <li>• Bedroom</li> <li>• Dining room</li> <li>• Dog kennels</li> <li>• Hallway</li> <li>• Internal walls</li> <li>• Kitchen</li> <li>• Laundry</li> <li>• Living room</li> </ul> <b>Commercial</b> <ul style="list-style-type: none"> <li>• Walls</li> </ul> <b>Industrial</b>
<b>Product images</b>	



IMG\_0122.jpg

Name	Wall Vent
Caption	Internal wall vent
Location	Domestic home
Source	Asbestos Education Committee
Image Id	43




IMG\_1264.JPG

Name	Wall Vent in kitchen
Caption	Wall Vent in kitchen
Location	Domestic home
Source	Asbestos Education Committee
Image Id	320



IMG\_1261.JPG

Name	Asbestos in the Bathroom
Caption	Asbestos cement sheeting in walls and ceiling, adhesive behind tiles, in grout and ceiling vent.
Location	Domestic home

Source	Asbestos Education Committee
Image Id	321
<div></div>	
IMG_1263.JPG	
Name	Asbestos vent in bathroom
Caption	Ceiling vent in bathroom
Location	Domestic home
Source	Asbestos Education Committee
Image Id	322

