

Product: Imitation brick cladding

Product Name Imitation brick cladding

Product type Cement - sheets, moulded product

Sub-Product type

Trading name(s)

Other name(s)

Product description The imitation brick may contain asbestos, however the sheeting located behind was commonly asbestos containing sheeting. The imitation brick was commonly nailed onto the asbestos sheeting.

Build element Construction

Product identification

The texture is not as rough as real brick.

Known uses Internal and exterior decoration. Most commonly attached to asbestos containing cement sheeting.

Asbestos fibre type

Friable or Non-Friable Non-Friable

Known Supplier(s)

Known place of manufacture

Date / period of manufacture Pre 1987

Building construction period 1951-1960,1961-1970,1970-1980,1981-1990

Location **Domestic home**

- Bathroom
- Exterior
- Internal walls

Product images



Fake Brick Cladding_0696c.jpg

Name Imitation brick cladding - exterior

Caption Exterior imitation / fake brick cladding and asbestos cement eaves

Location Domestic home

Source Asbestos Education Committee

Image Id 226



Fake Brick Cladding_0700.jpg

Name Imitation brick cladding - exterior

Caption Close up of exterior imitation / fake brick cladding. The asbestos cement sheeting is visible.

Location

Source Asbestos Education Committee

Image Id 227



JBIFake Brick Cladding - Confirmed (2).jpg


Name Imitation brick sheeting - internal wall

Caption Imitation brick sheeting within a domestic living room.

Location Domestic home

Source Jim's Building Inspections

Image Id 228



JBI_Fake Brick Cladding - Confirmed.jpg

Name Imitation brick sheeting - internal wall

Caption Imitation brick sheeting within a domestic living room.

Location Domestic home

Source Jim's Building Inspections

Image Id 229



DSC_0553.JPG


Name Imitation brick cladding - exterior

Caption Exterior imitation / fake brick cladding. Asbestos cement sheeting is behind the fake bricks.

Location Domestic home

Source Asbestos Education Committee

Image Id 233



DSC_0554.JPG

Name Imitation brick cladding - exterior close up

Caption Close up of imitation brick cladding on the broken exterior window ledge which shows the asbestos cement sheeting behind the fake brick.

Location Domestic home

Source Asbestos Education Committee

Image Id 234



DSC_0556.JPG

Name Imitation brick cladding - exterior

Caption Exterior imitation / fake brick cladding. Asbestos cement sheeting is behind the fake bricks.

Location Domestic home

Source Asbestos Education Committee

Image Id 235

